



The Smart Valve Customer Case Study

Property Name: Park Avenue Apartments

Location: 5100 Park Avenue, West New York, NJ

Property Description: Apartments & Commercial

Water Source/Provider: Municipal **Meter Size:** 1”

Source: Management Company

Documented Consumption - Prior to installation: **Gallons Per Diem: 2,930.**

Documented Consumption - After installation: **Gallons Per Diem: 2,150.**

Comments: Vacancy constant under 2.5%

Reduction Percentage: 30%

Out of respect for the client, please do not attempt to make contact without obtaining permission.